ESEPRO Firmware Release History

Feature "MFR2 Emulation"

V3.0.3

- Added MFR2 Emulation

Feature "TPDO objects"

V2.3.3

- Improved operation with Y-Link (reworked Profibus parameterization and diagnostic, allow duplicate Prm and Cfg Profibus telegrams)

V2.2.0

- Profibus Station address can be set via web interface

V2.1.0

- Bug fix relating TPDO objects (output image consumption count was only half, COB-IDs which have not been configured as RXPDO as well caused assertion failure)

V2.0.1

- Added TPDO (Transmit PDO) functionality

- Bug fix for Read and Write Parameter commands (input image shift and commands 241,242 and 244 returned wrong response (244) upon completion)

Original feature set

V1.1.0

- Initial firmware shipped with first production batch